

## Failed Schools

**Butler School** 1140 Gorham St - 3/12/19 No hot water at hand sink / Follow-up inspection 3/14/19 – Repaired.

**Robinson School** 110 June St – 3/14/19 Mice / Banner serviced 3/14/19 2:45pm Missing and damaged ceiling tiles.

**Wang School** 365 West Meadow Rd 3/14/19 Missing drywall in dry storage and office - Damaged wall in loading area - Mold/Mildew around loading door.

**Pawtucket Memorial** 425 West Meadow Rd 3/14/19 Active leak in dry storage.

**Daley School** 145 Fleming St – 3/20/19 - Fire Suppression System tagged non-compliant.

**Courtyard Restaurant (LHS)** – 30 Kirk St – Leak in dishwasher booster – Porous surface below and above dishwasher / Area needs to be cleaned and sealed or install smooth non-porous paneling around dishwasher.